

EPA Lead Renovator, Repair and Painting Rule

Beginning April 22, 2010, all renovators, remodelers, painters, maintenance personnel and any other workers removing or modifying painted surfaces in pre-1978 child/pregnant woman-occupied facilities or Federally-assisted target housing must obtain EPA certification as a Certified Renovator (www.epa.gov/lead). Firms who conduct lead based paint activities and/or renovations must be certified by EPA through submission of application and payment of fees by this deadline [40 CFR 745.89(a)]. The application is located at: <http://www.epa.gov/lead/pubs/firmapp.pdf>. The deadline for training and certification is rapidly approaching. Please inform your clients involved in these activities about the new regulatory requirements.

Santa Fe Community College received EPA certification to provide accredited Certified Renovator and Certified Lead Dust Sampling Technician courses in January 2010. For information regarding these courses, contact Jeanne-Marie Crockett at (505) 428 1414 or JeanneMarie.Crockett@sfcc.edu. Janet Kerley, CHMM is currently the Lead Pb Trainer for these courses (505 856 8543 or janet@lrnm.com), if you have questions regarding the regulatory requirements.